

MATERIAL SAFETY DATA SHEET (MSDS)

Substance

HSE-39A No Flux

Revision Date : Sep/ 03/ 2021

1 CHEMICAL PRODUCT AND COMPANY IDENTIFICATION

1. CHEMICAL PRODUCT AND	COMPANY IDENTIFICATION
A. PRODUCT NAME	HSE-39A No Flux
B. MATERIAL	: METAL ALLOY
C. PRODUCT'S USE	: SOLDER, SOLDERING
D. MANUFACTURE'S NAME	: LT Materials Co.,Ltd.
E. ADDRESS	: 113-19,Dangha-ro, Namsa-Myeon, Cheoin-Gu, Yongin-Si,
	Gyeonggi-Do, Korea
	Tel : 82- 31- 330- 1000
	Fax : 82-31- 335 – 6205~6
HAZARD IDENTIFICATION	
A. PRODUCT HAZARD CLAS	S
Skin hypersensitivity Class :	1
Specific target organ toxicity	(single exposure) Class : 2 (respiratory system)
Specific target organ toxicity	r (repeated exposure) Class : 1
Aquatic environmental toxici	ty.Long-term : Class : 3
B. LABEL COMTENT	
SIGNAL : Danger	
HAZARD WORD	
H317 May cause an aller	-
H371 May cause damage	
-	organs through prolonged or repeated exposure
H373 May cause damage	to organs through prolonged or repeated exposure

-. PREVENTION WORD

□ PREVENTION

P260 Do not breathe dust/fumes/gas/mist/vapours/spray.

P264 Wash ... thoroughly after handling.

P270 Do not eat, drink or smoke when using this product.

P272 Contaminated work clothing should not be allowed out of the workplace.

P280 Wear protective gloves/protective clothing/eye protection/face protection. [As modified by IV ATP]

P302+352 IF ON SKIN: Wash with plenty of water/... [As modified by IV ATP]

P308+311: If exposed or concerned: Call a POISON CENTER/ doctor/... [Added by IV ATP]

P314: Get medical advice/attention if you feel unwell.

P333+313 IF SKIN IRRITATION OR A RASH OCCURS: GET MEDICAL ADVICE/ATTENTION.

P362+364: Take off contaminated clothing and wash it before reuse. [Added by IV ATP]

P405 Store locked up.

P501 Dispose of contents/ container to an approvedlandfill

C. OTHER HAZARD

: No information

3. COMPOSITION, INFORMATION ON INGREDIENTS

Chemical name	Contents	CAS No.
Tin	REM	7440-31-5
Silver	0.8 ~ 1.2%	7440-22-4

4. FIRST AID MEASURES

A. In case of eye contact

Get medical advice and attention if you feel unwell.

 ${\bf B}.$ In case of skin contact

Wash with plenty of soap and water.

Get medical advice and attention if you feel unwell.

If skin irritation or rash occurs, get medical advice and attention.

Take off contaminated clothing and wash it beforereuse

C. In case of inhalation

Get medical advice and attention if you feel unwell.

D. In case of ingestion

Get medical advice and attention if you feel unwell.

Ε.	Most important symptoms/effects, acuteand delayed
	If inhaled : Wheezing.
	The effect through prolonged or repeated exposure : May cause eye, nose, throat, skin discoloration.
	Eye / skin redness, ocular pain, cough, headache, shortness of breath, sore throat,
	abdominal pain,nausea, vomiting.
	Delayed symptom : Metal fume fever.
F.	Indication of immediate medical attentionand special treatment needed, if necessary
	Rest and medical follow-up are indispensable.
5. FI	RE FIGHTING MEASURES
Α.	Suitable extinguishing media
	Small fires: Dry chemical, CO2 or water spray.
	Large fires: Water spray, fog or regular foam.
В.	Prohibited media :
	Water
C.	Specific hazards with regard to fire-fighting :
	No information
D.	Protection for firefighters :
	Fighters should wear protective clothing, respirator, rubber boots and fireproof clothing.
	And should work from the windward side.
6. AC	CIDENTAL RELEASE MEASURES
Α.	Personal precautions, protective equipmentand emergency procedures :
	Do not touch or walk through spilled material.
В.	Environmental precautions :
	Pay attention not to cause the influence on theenvironment by discharging into rivers.
	Do not release into the environment.
С.	Methods and materials for containment and cleaning up :
	Gather up, pack in a bag and dispose. Carefully collect remnant and move to a safe place.
7. H/	ANDLING AND STORAGE
Α.	Handling
	Technical measures :
	Provide ventilation system and use necessarypersonal protective equipment as described in
	in"Section 8 - EXPOSURE CONTROLS / PERSONALPROTECTION".
	Safe handling advice :
	Prohibit use of heat, sparks, and fire in thesurrounding area.
	Evacuate area due to explosion risk in case of fire.
	Do not subject to rough handling such as grinding, shock and friction.
	Do not contact, breathe or swallow
	Use only outdoors or in a well-ventilated area.
	Contaminated work clothing should not be allowed outof the workplace.

Avoid release to the environment.

Hygiene measures :

Wash hand thoroughly after handling.

Do not eat, drink or smoke when using this product.

B. Storage

Suitable storage conditions :

The storage facility should be designed with fire-proofconstruction and beams should use a non-combustible material.

The storage floor should be protected from waterpenetration, or should have water-proof construction.

The storage facility should be provided withnecessary lighting, lighting equipment, and ventilator store and handle dangerous goods.

Keep away from heat, sparks, open flames and hotsurfaces. No smoking.

Store away from oxidants

Store in a well-ventilated and cool place keepingcontainer tightly closed.

Protect from sunlight.

Store locked up.

Refer to "Section 10 - STABILITY ANDREACTIVITY".

8. EXPOSURE CONTROLS / PERSONAL PROTECTION

A. Control parameters

Material name	ACGIH (TLV)	OSHA (PEL)
Tin	2mg/m3	2mg/m3
Silver	0.1mg/m3	0.01mg/m3

B. Engineering measures

Workplace storing or handling this product should beequipped with eyewashing station and safety shower. Install ventilation system to keep exposure to airbornecontaminants below the exposure limit if dust and and fume generate in the process handling at elevatedtemperature.

C. Personal protective equipment

Respiratory protection : If necessary, wear appropriate respiratory protectiveequipment.

Hand protection : Wear appropriate protective gloves.

Eye protection : Wear appropriate protective glasses (ordinary glassestype, ordinary glasses type with side plates, goggletype)

Skin and body protection : Wear suitable protective clothing and face protection.

Specific hygiene measures : Provide eye washing tools and safety shower.

9. PHYSICAL AND CHEMICAL PROPERTIES

- A. Appearance : Solder Wire
- B. Color : Grey
- C. Odor : Scentless
- **D.** Odor threshold : No data

 G. Boiling H. Flash I. Flamm J. Flamm K. Vapor L. Vapor M. Relativ N. Specif O. Resolution Q. Partition R. Auto-in S. Decord T. Viscos STABIL A. Stability Stable B. Reaction May restance C. Hazard Non-peer E. Materia Strong 	ig point : 227 °C g point : No data point : No data nability(Solid,Gas) : nability or explosive r pressure : No data r density : No data ve density : No data ve density : No data fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa ignition temperature mposition temperature mposition temperature ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	limits : No data No data hence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 G. Boiling H. Flash I. Flamm J. Flamm K. Vapor L. Vapor M. Relativ N. Specif O. Resolution Q. Partition R. Auto-in S. Decord T. Viscos STABIL A. Stability Stable B. Reaction May restance C. Hazard Non-peer E. Materia Strong 	g point : No data point : No data nability(Solid,Gas) : nability or explosive r pressure : No data r density : No data ve density : No data ve density : No data fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa gnition temperature mposition temperature mposition temperature ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	limits : No data No data hence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 H. Flash I. Flamm J. Flamm K. Vapor M. Relative N. Specified O. Resolution Q. Partition R. Auto-intion S. Decord T. Viscos STABIL A. Stability Stable B. Reaction May rest C. Hazardon Non-period E. Materiation Strong 	point : No data nability(Solid,Gas) : nability or explosive r pressure : No data r density : No -pertine r on coefficient: n-octa ignition temperature mposition temperature mposition temperature mposition temperature LITY AND REACTI ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	limits : No data No data hence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 Flamm Flamm K. Vapor L. Vapor M. Relativ N. Specif O. Resolution Q. Partition R. Auto-in S. Decord T. Viscos STABIL A. Stability Stable B. Reaction May restrict C. Hazard Non-peer D. Condity Non-peer E. Materiation 	nability(Solid,Gas) : nability or explosive pressure : No data r density : No data ve density : No data fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa ignition temperature mposition temperature sity : Non-pertinence _ITY AND REACTI ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	limits : No data No data hence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
J. Flamm K. Vapor L. Vapor M. Relativ N. Specif O. Resolut P. Solubi Q. Partitio R. Auto-in S. Decor T. Viscos . STABIL A. Stabilit Stable B. Reactio May re C. Hazard Non-pe D. Condit Non-pe E. Materia	nability or explosive pressure : No data density : No data ve density : No data fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa ignition temperature mposition temperature mposition temperature sity : Non-pertinence LITY AND REACT ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	limits : No data No data hence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 K. Vapor L. Vapor M. Relativ N. Specif O. Resolution Q. Partition R. Auto-in S. Decord T. Viscos STABIL A. Stability Stable B. Reaction May rest C. Hazard Non-peer D. Condity Non-peer E. Materia Strong 	r pressure : No data r density : No data ve density : No data fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa ignition temperature mposition temperature mposition temperature ITY AND REACTI ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	No data nence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 L. Vapor M. Relativ N. Specifi O. Resolution Q. Partition Q. Partition R. Auto-inition S. Decorrist S. Decorrist S. Decorrist S. Decorrist S. TABIL A. Stability Stable B. Reaction May rest C. Hazardon Non-period D. Condition Non-period E. Materian Strong 	r density : No data ve density : No data fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa ignition temperature mposition temperature mposition temperature sity : Non-pertinence .ITY AND REACT ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	No data nence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 N. Specif O. Resolution P. Solubia Q. Partition R. Auto-in S. Decord T. Viscos STABIL A. Stability Stable B. Reaction May restrict C. Hazard Non-period D. Condition Non-period E. Materiation Strong 	fic gravity : 7.4 ution temperature : ility(ies) : Non-pertir on coefficient: n-octa ignition temperature mposition temperature sity : Non-pertinence LITY AND REACTION ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	No data nence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 O. Resolution P. Solubia Q. Partition R. Auto-in S. Decorn T. Viscos STABIL A. Stabilities B. Reaction May restrict C. Hazard Non-period D. Condition Non-period E. Materian Strong 	ution temperature : ility(ies) : Non-pertin on coefficient: n-octa ignition temperature mposition temperature sity : Non-pertinence _ITY AND REACTI ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	nence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 P. Solubi Q. Partition R. Auto-in S. Decorn T. Viscos STABIL A. Stability Stable B. Reaction May restand C. Hazardon Non-period D. Condition Non-period E. Materiation 	ility(ies) : Non-pertin on coefficient: n-octa ignition temperature mposition temperature sity : Non-pertinence LITY AND REACTION ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	nence anol/water : Non-pertinence : Non-pertinence ure : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 Q. Partition R. Auto-in S. Decondition T. Viscos STABIL A. Stabilities B. Reaction May redistrict C. Hazard Non-peering D. Condition Non-peering E. Materian Strong 	on coefficient: n-octa ignition temperature mposition temperature sity : Non-pertinence ITY AND REACTI ty : in the air at the norn ons : eact with strong oxidi dous decomposition ertinence	anol/water : Non-pertinence : Non-pertinence e IVITY mal temperature. izing compound, acids and	
 R. Auto-in S. Decor T. Viscos STABIL A. Stability Stable B. Reacting May restrict May restrict Mon-period D. Condity Non-period E. Materia Strong 	ignition temperature mposition temperature sity : Non-pertinence LITY AND REACTION ty : in the air at the norm ons : eact with strong oxidi dous decomposition ertinence	 Non-pertinence Non-pertine Non-pertinence Non-pertinence	
 S. Decor T. Viscos STABIL A. Stabilit Stable B. Reaction May re C. Hazaro Non-pe D. Condition Non-pe E. Materian Strong 	mposition temperatu sity : Non-pertinence ITY AND REACTI ty : in the air at the nor ons : eact with strong oxidi dous decomposition ertinence	ire : Non-pertinence e IVITY mal temperature. izing compound, acids and	strong bases.
 T. Viscos STABIL A. Stabilit Stable B. Reaction May resident C. Hazardon Non-peesition D. Condition Non-peesition Strong 	sity : Non-pertinence ITY AND REACTING ty : in the air at the norm ons : eact with strong oxiding dous decomposition ertinence	e IVITY mal temperature. izing compound, acids and	strong bases.
. STABIL A. Stabilit Stable B. Reactio May re C. Hazaro Non-pe D. Condit Non-pe E. Materia Strong	LITY AND REACT ty : in the air at the nor ons : eact with strong oxidi dous decomposition ertinence	IVITY mal temperature. izing compound, acids and	strong bases.
 A. Stabilit Stable B. Reaction May resident of the stability C. Hazaro Non-pee D. Condition Non-pee E. Materia Strong 	ty : in the air at the norr ons : eact with strong oxidi dous decomposition ertinence	mal temperature. izing compound, acids and	strong bases.
Stable B. Reaction May re C. Hazaro Non-pe D. Condition Non-pe E. Materia Strong	in the air at the norr ons : eact with strong oxidi dous decomposition ertinence	izing compound, acids and	strong bases.
 B. Reaction May reaction May reaction Non-period D. Condition Non-period E. Materia Strong 	ons : eact with strong oxid dous decomposition ertinence	izing compound, acids and	strong bases.
May re C. Hazaro Non-pe D. Condit Non-pe E. Materia Strong	eact with strong oxidi dous decomposition ertinence		strong bases.
 C. Hazaro Non-pe D. Conditi Non-pe E. Materia Strong 	dous decomposition ertinence		strong bases.
Non-pe D. Condit Non-pe E. Materia Strong	ertinence	products :	
 D. Condit Non-pe E. Materia Strong 			
Non-pe E. Materia Strong			
E. Materia Strong	tions to avoid :		
Strong	ertinence		
	als to avoid :	the the second second	
		d, acids and strong bases.	
	DLOGICAL INFO	RMATION	
A. Acute	toxicity : No data		
<u> </u>	Material name	Oral LD50	Skin LD50
	Silver	>5000 mg/Kg(Rat)	>2000mg/Kg(Rat)
B. Skin co	orrosive / irritation :	No data	
C. Seriou	s eyes damage /Eye	es irritation : No data	
D. Respir	atory organs sensitiz	zation :	
When	fume inhales, may c	cause allergy, edge breath o	or dyspnea.
E. Skin se	ensitization : May ca	ause allergy skin reaction.C	Class 1
F. Origina		riation . No data	
G. Carcin	al generative cell vai	Halloff · NO Gala	
H. Reproc	al generative cell vai ogenicity:No inforr		

15. REGULATORY INFORMATION

- A. Regulation by Chemical Substance Control Act : Not applicable
- B. Regulation under dangerous goods safety management law : Not applicable
- C. Regulation by waste management law : designated wastes

E. Other domestic and foreign regulations : Not applicable

16. OTHER INFORMATION

A. The information contained in this data sheet does notconstitute an assessment of workplace risks. Theabove information is based on the present state ofour knowledge of the product at the time ofpublication It is given in good faith, no warranty is implied with the respect to the quality or the specification of the product The user must satisfy himself that the product is entirely suitable for his purpose.